

ARRIVAL ROUTE DESCRIPTION

KPBI: From SHRVY on track 093° to ROKSY, then on track 093° to cross TARTY between 9000 and 11000 and at 250K, then on track 116° to cross HLIBT at or below 9000.

LANDING KPBI RUNWAY 10L, 14: From HLIBT on track 117° to cross GULLO at 5000. Expect ILS or LOC Rwy 10L or RNAV (RNP) Z Rwy 14 approach.

LANDING KPBI RUNWAY 28R, 32: From HLIBT on track 118° to cross JANDS at or above 8000, then on track 118° to cross BEKAH at 6000, then on track 099° to cross COTEB at 6000 and at 210K, then on track 099°. Expect RADAR vectors to final approach course.

LANDING 06FA/F45: From SHRVY on track 093° to ROKSY, then on track 093° to cross OWLL at 9000 and at 250K, then on track 090° to YIGBO, then on heading 093° or as assigned by ATC. Expect RADAR vectors to final approach course.

LANDING KBCT: From SHRVY on track 093° to ROKSY, then on track 093° to cross OWLL at 9000 and at 250K, then on track 159° to VETCH, then on track 111° to DIZAM, then on heading 091° or as assigned by ATC. Expect RADAR vectors to final approach course.

LANDING KSUA: From SHRVY on track 093° to ROKSY, then on track 093° to cross OWLL at 9000 and at 250K, then on track 032° to MSQTO, then on heading 051° or as assigned by ATC. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS

KPBI Landing Rwy 10L/14: Continue track to GULLO, then proceed direct to WILBA, conduct ILS or RNAV 10L approach.

KPBI Landing 28R/32: Continue track to COTEB, then proceed direct to CUPED, conduct ILS or RNAV 28R approach.